

- Transfers parts between two flip pallets and a W-2200 SMD Crystal Disc
- Can be configured to unload only, load only, or unload and load W-2200 SMD Crystal Discs
- Simple flip pallets transfer SMD parts in and out of seam welder pallets
- Failures are binned into 1 of 4 bins using USB disc file from W-2200



### TYPICAL THROUGHPUT

<b>Load Only:</b>	1.4 sec per part
<b>Unload Only:</b>	1.4 sec per part
<b>Unload and Load:</b>	2.8 sec to unload one part and load one part